

Message

---

**From:** Benoit, Simonne T [Simonne.Benoit@arcelormittal.com]  
**Sent:** 1/16/2017 3:44:59 PM  
**To:** sean.fitzgerald@uscg.mil; Beslow, Mike [beslow.mike@epa.gov]  
**CC:** Barnett, Thomas R [Thomas.Barnett@arcelormittal.com]  
**Subject:** Status update 009/010/001  
**Attachments:** IMG\_00000481.jpg; IMG\_00000480.jpg

Boom Changed:

- 4 bags total on 1/15

Observations:

- Observed 009/010 from 7:30AM-8:30AM. Conditions normal. Occasional quarter pops, some sheen between outer hard boom (orange) and inner soft boom, all contained. Observed National change soft boom in the dock side corner of the outer boom. Plan is to clean and replace inner hard boom (yellow) today.
- Observed 001 from 8:45AM-8:52AM. All conditions appeared the same as on 1/13.

Per the Coast Guard's 1/15/17 request, attached are two photos from this morning at 009/010.

**Simonne T. Benoit** | Environmental Engineer  
ArcelorMittal Indiana Harbor LLC | ArcelorMittal USA LLC

MEU Environmental | 3001 Dickey Road, Sta. 001  
East Chicago, IN 46312

T +219 399 2109 | F +219 399 3211 | M +219 313 5069 | [www.arcelormittal.com](http://www.arcelormittal.com)